


NOTES:

- 1.) SEDIMENT TRAPPED UPSTREAM OF SEDIMENT CONTROL BMP SHALL BE REMOVED WEEKLY AND PRIOR TO A RAINFALL EVENT.
- 2.) PLACE BMP'S TIGHTLY TOGETHER AT JOINTS TO PREVENT SEEPAGE AT JOINTS.
- 3.) AT A MINIMUM, BMP'S MUST BE INSPECTED WEEKLY, PRIOR TO FORECASTED RAIN EVENTS, DAILY DURING EXTENDED RAIN EVENTS, AND AFTER THE CONCLUSION OF RAIN EVENTS.



DIRECTOR, DEPARTMENT OF WATER RESOURCES

COUNTY OF SACRAMENTO

INLET SEDIMENT CONTROL

DRAWN BY: STAFF
SCALE: NONE
DATE: 09/2024

11-7